Annexure D

BUILDING SAFETY CERTIFICATE

| Nico | 700 | 0 |
|------|-----|----|
| No | 179 | -8 |

Dated: 15-06-2024

It is certified that the existing building Mangu Choudhary Memoral School name of the building or premises) at That bihat chowk pupri

... (address) is having block(s)/Floor(s) as per details below

| Detail of Block(s) in | Block | Disas | 1 | | | |
|--------------------------------|-------|--------------|-----------|----------------|--------------|-------|
| school | (1) | Block (2) | Block (3) | Block (4) four | Block (5) | Blork |
| No of Floor(s) in the Block | | 2 Hoors. | | 4 (four) | | |

The building is owned/occupied by Mangu Chaudhang Tromonal School. of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Executive Engineer, &D (Name of Govt.) on 14/06/2024 (date of inspection) of Chairman of Manay Chandham Memana School (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for with rule and subject to compliance of the specific conditions as appended.

1. The building is sofe as bound of viow of strongth.
2 the railing is found at staircate.
3 time Entinguisher is installed in Building.

Issued on 15.06.2024 at 11:00 A:M by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for defail

Smaj chandham 4

Signature with Seal

Designation : भवन प्रमण्डल सीतामढी

Name & Address of Department/ Office

68 |

Principal Manju Choudhary Memorial School Pupri, Sitamarhi-843320

Soully Miner Manju Choudhary Memorial School Pupri, Sitamarhi-843320